



Forum: Hardware

Topic: Siemens GIGASET USB Adapter 108

Subject: Siemens GIGASET USB Adapter 108

Poslao: kenny

Postano : 26.02.2006 22:09:19

Molim pomoc oko instalacije navedene wlan kartine

pokisao sam s ndiswrapper om ali ocito nisam dovoljno upucen

uz pomov lsusb sam odbio

Bus 002 Device 003: ID 04b4:6830 Cypress Semiconductor Corp. USB-2.0 IDE Adapter

Bus 002 Device 002: ID 129b:160c

Bus 002 Device 001: ID 0000:0000

Bus 001 Device 001: ID 0000:0000

Sto znaci da bi trebao sljediti ovo

Card: SIEMENS GIGASET USB 108 ADAPTER

* Chipset : Atheros 5523

* usbid: 129b:160c

* Drivers: athfmwdl + net5523 (unsure if both are needed) from CD provided with device

* Other: Tested with ndiswrapper 1.10; WPA works; 108 MB/s seems to work, too.

I nakon istalacije tih drivera ndiswrapper izgleda ...

\$ ndiswrapper -l

Installed ndis drivers:

athfmwdl driver present, hardware present

net5523 driver present, hardware present

nakon sto napravim depmod -a i modprobe dodje do sljedece greske

[4295687.822000] ndiswrapper version 1.1 loaded (preempt=no,smp=no)

[4295688.072000] ndiswrapper (import:238): unknown symbol: ntoskrnl.exe:ZwReadFile

[4295688.072000] ndiswrapper (import:238): unknown symbol: ntoskrnl.exe:ZwQueryInformationFile

[4295688.072000] ndiswrapper (import:238): unknown symbol: ntoskrnl.exe:ZwCreateFile

[4295688.072000] ndiswrapper (import:238): unknown symbol:

ntoskrnl.exe:IoSetDeviceInterfaceState

[4295688.072000] ndiswrapper (import:238): unknown symbol: ntoskrnl.exe:IoDetachDevice
[4295688.072000] ndiswrapper (import:238): unknown symbol: ntoskrnl.exe:PoSetPowerState
[4295688.072000] ndiswrapper (import:238): unknown symbol: ntoskrnl.exe:PoRequestPowerIrp
[4295688.072000] ndiswrapper (import:238): unknown symbol: ntoskrnl.exe:KeQuerySystemTime
[4295688.072000] ndiswrapper (import:238): unknown symbol: ntoskrnl.exe:IoBuildPartialMdl
[4295688.073000] ndiswrapper (import:238): unknown symbol: ntoskrnl.exe:KeInitializeTimerEx
[4295688.073000] ndiswrapper (import:238): unknown symbol:
ntoskrnl.exe:IoRegisterDeviceInterface
[4295688.073000] ndiswrapper (import:238): unknown symbol:
ntoskrnl.exe:IoAttachDeviceToDeviceStack
[4295688.073000] ndiswrapper (import:238): unknown symbol: ntoskrnl.exe:KeInsertQueueDpc
[4295688.073000] ndiswrapper (import:238): unknown symbol: ntoskrnl.exe:KeRemoveQueueDpc
[4295688.073000] ndiswrapper (import:238): unknown symbol: ntoskrnl.exe:wcslen
[4295688.073000] ndiswrapper (import:238): unknown symbol: WMILIB.SYS:WmiSystemControl
[4295688.073000] ndiswrapper (import:238): unknown symbol: WMILIB.SYS:WmiCompleteRequest
[4295688.073000] ndiswrapper (load_sys_files:456): unable to prepare driver 'athfmwdl'
[4295688.318000] ndiswrapper (ndiswrapper_load_driver:92): loadndiswrapper failed (6); check
system log for messages from 'loadndisdriver'
[4295688.318000] usbcore: registered new driver ndiswrapper

i wlan0 se ne pojavi ... ima li tko ideju